

# Design FMEA

Revision 6.0 2/11/98

<input type="checkbox"/> System <input type="checkbox"/> Subsystem <input checked="" type="checkbox"/> Component	<b>Customer</b> Chrysler Motors Corporation	<b>Customer Part No.</b> DC-77323-XYZ	<b>Org. Date</b> 2/11/98	<b>Page</b> 1 of 2
	<b>Supplier</b> Any Company, Inc.	<b>Code</b> ACI-001	<b>Supplier Part No.</b> A-9514	<b>Dwg. Rev.</b> 8
<b>Part Name</b> Filter		<b>Design Responsibility</b> Brad Anderson		<b>Key Date</b> 2/11/98
		<b>Application/Model Year</b> Sedan / 1998		
<b>Core Team</b> Brad Anderson, Jerry Benware, Lisa Brown, Ken Caracci, Bill Cox, Fred Jordan, Ken Kratz				<b>Prepared By</b> Brad A. Anderson
				<b>Date</b> 2/11/98

Item / Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v	C l a s s	Potential Cause(s) / Mechanisms of Failure	O c c u r	Current Design Controls	D e t e c	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S e v	O c c	D e t	R. P. N.
Filter for assembly with B44 to firewall	Insufficient wax coverage over specified surface	Deteriorated life of door leading to: Unsatisfactory appearance due to rust through paint over time, Impaired function of interior door hardware	4	◇	Insufficient wax thickness specified	4	Supplier certification	1	16	None	N/A 2/11/98					
					Inappropriate wax specified	5	set up set up	4	80							
						5	Five piece setup, in-process, end of run study	2	40	None	N/A 2/11/98					
Corroded interior lower door panels	Improper oxide coating	Improper oxide coating	6	☹	Entrapped air prevents wax from entering corner/edge access	6	Test spray pattern at startup and after idle periods, and ...	5	180	Add team evaluation using production spray equipment and specified wax	Engineering and Assembly Operations 2/18/98	Based on test results (Test #9989) spray head modified to ...	6	2	5	60
					Spray heads clogged: Viscosity too high, Temperature too low, Pressure too low	4	Incomming audit per 200-16 certification, SPC Lot/Qtr	2	48							
						4	Laboratory test using "worst case" wax and application hole size	3	72	Add laboratory accelerated corrosion testing	ABC Labs 2/27/98	Test results show specified ...	6	3	3	54
								3	72	Conduct DOE on wax thickness	Engineering Associates 2/18/98	DOE shows 25% variation in specified thickness is acceptable	6	2	2	24
		Feeder not properly or	3													

	<b>Approved By</b> Brad A. Anderson	<b>Date</b> 2/11/98
--	--	------------------------

# Design FMEA

Revision 6.0 2/11/98

<input type="checkbox"/> System <input type="checkbox"/> Subsystem <input checked="" type="checkbox"/> Component	Chrysler Motors <b>Supplier</b> Any Company, Inc.	<b>Code</b> ACI-001	<b>Customer Part</b> DC-77323-XYZ <b>Supplier Part No.</b> A-9514	<b>Dwg. Rev.</b> 8	<b>Org.</b> 2/11/98	2 of 2 <b>Key Date</b> 2/11/98 <b>FMEA No.</b> DFMEA-001
<b>Part Name</b> Filter			<b>Design Responsibility</b> Anderson		<b>Application/Model Year</b> Sedan / 1998	
<b>Core Team</b> Brad Anderson, Jerry Benware, Lisa Brown, Ken Caracci, Bill Cox, Fred Jordan, Ken Kratz				<b>Prepared By</b> Brad A. Anderson		<b>Date</b> 2/11/98

Item / Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v	C l a s s	Potential Cause(s) / Mechanisms of Failure	O c c u r	Current Design Controls	D e t e c	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S e v	O c c	D e t	R. P. N.
		Customer complaint, rework	7	⬆	Inappropriate wax specified	5	aid investigation non-functioning spray	4	140	startup procedure	engineering					
							Laboratory test "worst case" and application size		5							
							Laboratory certification per 200-10		140							
				⬆	Entrapped air prevents wax from entering corner/edge access	4	Five piece setup, in-process, end of run study	4	112							

	<b>Approved By</b> Brad A. Anderson	<b>Date</b> 2/11/98
--	--	------------------------